

Inspection Photos

API: 071-07560

Operator: OGRIS OPERATING LLC

Inspection Date: 4/21/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07560 | Date: 4/21/2022

Inspection Photos



Photo 1. Facing west along the main access road. Additional gravel road base has been applied to areas of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 4/21/2022

Inspection Photos



Photo 2. The culverts along the road have been cleaned out and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 4/21/2022

Inspection Photos



Photo 3. Facing southeast along the main access road. Additional gravel road base has been applied to low areas of the road where water would accumulate.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 4/21/2022

Inspection Photos



Photo 4. The culverts along the road have been cleaned out and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 4/21/2022

Inspection Photos



Photo 5. Facing southeast along the main access road. Additional gravel road base has been applied to areas of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 4/21/2022

Inspection Photos



Photo 6. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07560 | Date: 4/21/2022