

Inspection Photos  
Location Name: Davies B #1  
API: 05-067-07838



Davies B #1 location photo.

Secondary containment for lube oil container and exhaust outlet.

**Inspection Photos**  
**Location Name: Davies B #1**  
**API: 05-067-07838**



**Lube oil is leaking onto the ground next to the secondary containment.**



**Davies B #1 well head.**