

Inspection Photos

April 18, 2022

Operator: Caerus Piceance LLC- #10456

Location ID: 323976

Location Name: Dunn-67S92W /4SWSE

Inspection Document #: 702800143

Garfield County, CO

SWSE Section 4 T7S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Dunn-67S92W /4SWSE
Location ID: 323976



Photo 1. Photo taken from the Location entrance facing northeast shows an overview of the Location.



Inspection Photos
Location Name: Dunn-67S92W /4SWSE
Location ID: 323976



Photo 2. Photo taken from tank battery facing west shows a lack of proper signage at the tank battery.

Inspection Photos
Location Name: Dunn-67S92W /4SWSE
Location ID: 323976



Photo 3. Photo taken from the south of the Location entrance facing northeast shows interim areas of the Location and adjacent undisturbed areas.



Inspection Photos
Location Name: Dunn-67S92W /4SWSE
Location ID: 323976



Photo 4. Photo taken from the north of the Location facing southeast shows interim areas of the Location.



Photo 5. Photo taken from the northeast of the Location facing northwest shows interim areas of the Location.