

Inspection Photos

April 18, 2022 and April 21, 2022

Operator: Caerus Piceance LLC- #10456

Location ID: 334853

Location Name: Shideler-66S92W /32SWNE

Inspection Document #: 702800145

Garfield County, CO

SWNE Section 32 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334853



Photo 1. Photo taken from the southwest of the Location facing northeast shows an overview of the Location.



Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334853



Photo 2. Photo taken from the tank battery shows a lack of required signage.



Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334853



Photo 3. Photo taken from the tank battery shows salt staining outside of secondary containment along the northeast side of the tank battery. Corrosion is apparent at the base of the metal containment



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800145

Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334853



Photo 4. Photo taken from the interim areas to the south of the Location facing north shows a lack of uniform, native, perennial plant establishment.



Photo 5. Photo taken from the interim areas to the southwest of the Location facing south shows the interim area dominated by undesirable plant species/weeds.



Inspection Photos
Location Name: Shideler-66S92W /32SWNE
Location ID: 334853



Photo 6. Photo taken from the interim areas to the southwest of the Location facing south shows the interim area dominated by annual wheatgrass, an introduced weed.



Photo 7. Photo taken from the interim areas to the southwest of the Location facing north shows the interim area dominated by bare ground and undesirable plant species/weeds.

