

BW Musser 1

05-081-05453

Docket No. 210400055

Semi-Annual LDAR Testing

TARGET  
ONLINE™

Company List

Administration

Change Password

Contact Us

Log Out

Emission

Repair Track

Assessment

Map View

Reports

Repair Management

Assessment List and Summary

EMISSION DETAIL REPORT  
EXPORT TO EXCEL

Facility: BW MUSSER 1; Assessment Date: 04/07/2022(Filtered 0 records/Total 0 records)

CLEAR ALL FILTER

▼ Summary

Dominion

Facility Name: BW MUSSER 1

Facility Location: 40.946396 / -108.311453

Assessment Date: 04/07/2022

Assessment ID: 3061649346121

Assessment Type(s): CO Reg 7

Technician (s): G Allen

Start Date: 2022-04-07 09:30:00.0

End Date: 2022-04-07 09:41:00.0

Instruments: Dominion 620GF OGI-1

Emissions Summary	Total	Repaired
Leaks:	0	0
Mandatory Leaks:	0	0
Vent: Repair Required	0	0
Vent: No Repair Required	0	-
Mandatory No Emissions:	0	-

All

Emission ID

Emission Type

Description

Safety Concern

Flow Rate (ft<sup>3</sup>/min)

Emission Severity

LDAR Tag #

PPM

Gas \$ /Year

Picture

Video

First Attempt Due Date

Final Repair Due Date

Repair Status

No emissions detected