

Inspection Photos
Operator: Kinder Morgan
API: 083-06379
Date: 4/21/2022



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing southwestward. Revegetation is progressing with western wheatgrass, sand dropseed, snakeweed, and rubber rabbitbrush.



Photo 3. View of the northern project area from the northern corner facing southwestward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of Indian ricegrass (*Achnatherum hymenioides*), sagebrush (*Artemisia tridentata*), muttongrass (*Poa fendleriana*), and bladderpod (*Physaria acutifolia*).