

Inspection Photos  
Operator: Kinder Morgan  
API: 083-06624  
Date: 4/21/2022



Photo 1. View of the project area facing northwestward from the approx. center of the well pad. Revegetation is progressing in portions with rubber rabbitbrush (*Chrysothamnus nauseosus*), crested wheatgrass (*Agropyron smithii*), and smooth brome (*Bromus inermis*).



Photo 2. View of the northern project area from the northeastern corner facing westward.





Photo 3. View of portion of the former well pad where sparse revegetation remains.





Photo 4. View of another portion of the former well pad where patches of bare soil remain.





Photo 5. View of access road will require reclamation before final reclamation is passed.



Photo 6. View of reference area comprised of sagebrush shrubland with sagebrush (*Artemisia tridentata*), Indian ricegrass (*Achnatherum hymenioides*), and James galleta (*Pleuraphis jamesii*).