

Inspection Photos
Operator: Kinder Morgan
API: 083-06593
Date: 4/21/2022



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with rubber rabbitbrush (*Chrysothamnus nauseosus*), crested wheatgrass (*Agropyron smithii*), western wheatgrass (*Pascopyrum smithii*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the western project area (foreground) and the reference area (background), facing southward, comprised of cultivated wheatfield.