

Inspection Photos
Operator: Kinder Morgan
API: 083-06195
Date: 4/21/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with rubber rabbitbrush (*Chrysothamnus nauseosus*), western wheatgrass (*Pascopyrum smithii*), Indian ricegrass (*Achnatherum hymenioides*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of the reference area comprised of pinyon and juniper woodland with banana yucca (*Yucca baccata*), sagebrush (*Artemisia tridentata*), Indian ricegrass (*Achnatherum hymenioides*), muttongrass (*Poa fendleriana*), and yellow cat's eye (*Cryptantha flavoculata*).