

Final Reclamation Inspection

April 12, 2022

Operator: PETERSON ENERGY OPERATING INC - #68710

Location ID: 322804

Inspection Document #: 697503881

Weld County, CO

NWSW Section 20 T7N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MAPELLI #5
Location ID: 322804



Photo 1. Photo taken from the northern access road, facing South. Photo illustrates the crop growth has uniform establishment which is reflective of reference areas.



Inspection Photos
Location Name: MAPELLI #5
Location ID: 322804



Photo 2. Photo taken from the northern access road, facing Southeast. See comments under Photo 1.



Photo 3. Photo taken from the northern access road, facing Southwest. See comments under Photo 1.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503881

Inspection Photos
Location Name: MAPELLI #5
Location ID: 322804



Photo 4. Photo taken from the associated offsite tank battery, facing South. Photo illustrates all equipment has been removed. Post plugging operations, midstream operations installed equipment which is not related to this location.



Inspection Photos
Location Name: MAPELLI #5
Location ID: 322804




Photo 5. Google Earth aerial imagery taken 9/12/2018 during active operations. Photo illustrates the tank battery and well location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503881

Inspection Photos
Location Name: MAPELLI #5
Location ID: 322804



Photo 6. Google Earth aerial imagery taken 7/17/2019 after plugging operations. Photo illustrates the former tank battery area is being disturbed, likely from midstream operations related to the new oil and gas location to the north.