

# Final Reclamation Inspection

April 22, 2022

Operator: OVERLAND RESOURCES LLC - #19035

Location ID: 319716

Inspection Document #: 697503887

Adams County, CO

NWSW Section 30 T2S R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: LEONA MARTIN #1  
Location ID: 319716



**Photo 1.** Photo taken from the southern access road, facing North. Photo illustrates the access road is reflective of reference crop area establishment.



**Photo 2.** Reference crop photo taken from the southern access road, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: LEONA MARTIN #1  
Location ID: 319716



**Photo 3.** Photo taken from the associated offsite tank battery, facing East. Photo illustrates the tank battery is reflective of reference areas.



Inspection Photos  
Location Name: LEONA MARTIN #1  
Location ID: 319716



**Photo 4.** Photo taken along a portion of the access road, facing South. See comments under Photo 3.



Inspection Photos  
Location Name: LEONA MARTIN #1  
Location ID: 319716



**Photo 5.** Photo taken from the well location, facing West. See comments under Photo 3.



**Photo 6.** Photo taken from the well location, facing North. See comments under Photo 3.

Inspection Photos  
Location Name: LEONA MARTIN #1  
Location ID: 319716



**Photo 7.** Photo taken from the well location, facing East. See comments under Photo 3.



**Photo 8.** Photo taken from the well location, facing South. See comments under Photo 3.

Inspection Photos  
Location Name: LEONA MARTIN #1  
Location ID: 319716



**Photo 9.** Rangeland reference photo taken east of the well location, facing Northeast.

