

Final Reclamation Inspection

December 15th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 323171

Inspection Document #: 701900358

NWNW Section 24 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Nadine 1-24
Location ID: 323171



Photo 1. 2021 aerial imagery of the well pad and tank battery (north is up). Note: The well pad now resides in an industrial lot. Area highlighted in blue was included in previous report but is now associated with the Noble tank battery disturbance #440949.

Inspection Photos
Location Name: Nadine 1-24
Location ID: 323171



Photo 2. Overview photo of the well pad taken from the eastern edge looking west.

Inspection Photos
Location Name: Nadine 1-24
Location ID: 323171



Photo 3. Overview photo of the tank battery taken at ground level from the eastern edge looking west. Photo shows that the tank battery has limited vegetation establishment and will need to be re-inspected when plants have fully established