

## Inspection Photos

Location Name: N. Parachute EF G29 595 pad and Remediation Project

Location ID: #335573 & Remediation Project #18188

Inspection Date: April 22, 2022



Photo #1 – Sign at entrance to pad.



Photo #2 – 80 bbl produced water AST on west end of pad.  
Note that secondary containment was filled with fluids on inspection date. No hydrocarbon sheens or odors were observed on fluids during inspection.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources



## Inspection Photos

Location Name: N. Parachute EF G29 595 pad and Remediation Project

Location ID: #335573 & Remediation Project #18188

Inspection Date: April 22, 2022



**Photo #3 – Mobile separator units located in southwest corner of pad.**



**Photo #4 – Mobile separator secondary containment device in need of repair.**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources



## Inspection Photos

Location Name: N. Parachute EF G29 595 pad and Remediation Project

Location ID: #335573 & Remediation Project #18188

Inspection Date: April 22, 2022



**Photo #5 - Mobile separator secondary containment device in need of repair.**



**Photo #6 - Mobile separator secondary containment device in need of repair.**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources



## Inspection Photos

Location Name: N. Parachute EF G29 595 pad and Remediation Project

Location ID: #335573 & Remediation Project #18188

Inspection Date: April 22, 2022



**Photo #7 - Mobile separator secondary containment device in need of repair.**



**Photo #8 - Mobile separator secondary containment device in need of repair.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: N. Parachute EF G29 595 pad and Remediation Project

Location ID: #335573 & Remediation Project #18188

Inspection Date: April 22, 2022



**Photo #9 – West cuttings cell in SE corner of pad is subject to REM #18188.**



**Photo #10 – East cuttings cell in SE corner of pad is subject to REM #18188.**



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources