

Inspection Photos

April 21, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 335228

Location Name: Benzel Disposal-66S93W /36NWNE

Inspection Document #: 702800153

Garfield County, CO

NWNE Section 36 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Benzel Disposal-66S93W
/36NWE
Location ID: 335228



Photo 1. Photo taken from the west of the Location facing northeast shows an overview of the Location.



Photo 2. Photo taken from the west of the Location facing southeast shows an overview of the Location.



Inspection Photos
Location Name: Benzel Disposal-66S93W
/36NWNE
Location ID: 335228



Photo 3. Photo taken from the southwest of the Location shows a small patch of knapweed established in the interim areas adjacent to the tank battery.



Inspection Photos
Location Name: Benzel Disposal-66S93W
/36NWNE
Location ID: 335228



Photo 4. Photo taken from the south of the Location facing west shows concrete forms no longer in use. Area requires interim reclamation.



Inspection Photos
Location Name: Benzel Disposal-66S93W
/36NWE
Location ID: 335228



Photo 5. Photo taken from the south of the Location facing east shows area requiring interim reclamation.



Photo 6. Photo taken from the south of the Location facing north shows area requiring interim reclamation.

Inspection Photos
Location Name: Benzel Disposal-66S93W
/36NWNE
Location ID: 335228



Photo 7. Photo taken from the northeastern interim area shows subsidence is occurring creating dangerous holes.



Photo 8. Refer to Photo 7 comment.

Inspection Photos
Location Name: Benzel Disposal-66S93W
/36NWNE
Location ID: 335228



Photo 9. Photo taken from the southwestern interim area facing east shows interim areas with no issues.



Photo 10. Photo taken from the eastern interim area facing east shows interim areas with no issues.

Inspection Photos
Location Name: Benzel Disposal-66S93W
/36NWNE
Location ID: 335228



Photo 11. Photo taken from the northern interim area facing west shows interim areas with no issues.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702800153