

Inspection Photos

API: 061-06793

Operator: STRACHAN EXPLORATION

Inspection Date: 4/25/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06793 | Date: 4/25/2022

Inspection Photos



Photo 1. Facing southeast toward the wellsite. The location is mostly bare of vegetation and needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06793 | Date: 4/25/2022

Inspection Photos



Photo 2. Facing southwest toward the wellsite. The location is mostly bare of vegetation and needs to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06793 | Date: 4/25/2022

Inspection Photos



Photo 3. Most of the weed debris has been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06793 | Date: 4/25/2022

Inspection Photos



Photo 4. Sign post is not sufficient per 605.a. No other well sign was observed.

