

Inspection Photos

API: 061-06294

Operator: STRACHAN EXPLORATION

Inspection Date: 4/25/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06294 | Date: 4/25/2022

Inspection Photos



Photo 1. Facing east at the abandoned well site. All equipment has been removed. A uniform crop cover will need to be established. No crop was planted this year.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06294 | Date: 4/25/2022

Inspection Photos



Photo 1. Facing west at the abandoned well site. All equipment has been removed. A uniform crop cover will need to be established. No crop was planted this year.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06294 | Date: 4/25/2022