

Inspection Photos

ID: 150396

Operator: CHEMCO INC

Inspection Date: 4/25/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 150396 | Date: 4/25/2022

Inspection Photos



Photo 1. Facing southeast toward the tank battery. Berms have rebuilt around the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 4/25/2022

Inspection Photos



Photo 2. There is still oil stained soils that need to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 4/25/2022

Inspection Photos



Photo 3. The electric box lid has been closed and wired. The electric cable on the ground is still a safety concern and needs to be covered and protected.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 4/25/2022

Inspection Photos



Photo 4. Oil waste has been cleaned out at the pipe outlet and a plastic tub was added to control spill. The tub will need to be monitored and cleaned out if it fills with oily waste.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 4/25/2022

Inspection Photos



Photo 5. There is various unused unnecessary equipment/supplies being stored at the location. The barrel shown at red arrow contains burnt ashes. Burning is prohibited on the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 4/25/2022

Inspection Photos



Photo 6. Facing east at the location. There is various unused unnecessary equipment/supplies being stored at the location. All supplies not necessary for use on the location is prohibited.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 4/25/2022