

# Inspection Photos

API: 061-06041

Operator: WESTERN OPERATING COMPANY

Inspection Date: 4/25/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06041 - Date: 4/25/2022

## Inspection Photos



**Photo 1.** Facing west at the beginning of the access road which consists of undesirable weeds. The cattle guard has been removed but the access road is not reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06041 - Date: 4/25/2022

## Inspection Photos



**Photo 2.** Facing west toward the access road which needs to be decompacted and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06041 - Date: 4/25/2022



## Inspection Photos



**Photo 3.** Facing northwest toward the location. The electric line has been removed. The location has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06041 - Date: 4/25/2022

## Inspection Photos



**Photo 4.** North side of the location facing south. This area of the location is approximately 120'x120' and consist of only undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06041 - Date: 4/25/2022



## Inspection Photos



**Photo 5.** View of groundcover consisting of undesirable weeds (*Kochia* sp.) and no desirable vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06041 - Date: 4/25/2022



## Inspection Photos



**Photo 6.** Facing north toward the surrounding undisturbed area which consists of a uniform native vegetation cover.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06041 - Date: 4/25/2022