

Inspection Photos  
Location Name: Sack G Unit 1  
Location ID: 320295



Photo 1 WH .

Photo 2 WH

Inspection Photos  
Location Name: Sack G Unit 1  
Location ID: 320295



Colorado Oil & Gas Conservation Commission  
1341 E. 150th Ave. Bloomfield, CO 80023, USA  
30 85493 - 102 26611 1111 4th, 539  
04/27/2022 09:08:56



Colorado Oil & Gas Conservation Commission  
1341 E. 150th Ave. Bloomfield, CO 80023, USA  
30 85493 - 102 26611 1111 4th, 539  
04/27/2022 09:41:24

Photo 3 Chained off WH .

Photo 4 WH has been cut

Inspection Photos  
Location Name: Sack G Unit 1  
Location ID: 320295



Photo 5 cut off WH.



Photo 6 cut casing

Inspection Photos  
Location Name: Sack G Unit 1  
Location ID: 320295



Photo 7 Capped casing.

Photo 8 Capped casing