

Inspection Photos  
Location Name: Sack 8-11  
Location ID: 320509



Photo 1 WH .

Photo 2 WH

Inspection Photos  
Location Name: Sack 8-11  
Location ID: 320509



Photo 3 Chained off WH .

Photo 4 WH has been cut

**Inspection Photos**  
**Location Name: Sack 8-11**  
**Location ID: 320509**



**Photo 5 cut off WH.**



**Photo 6 cut casing**

Inspection Photos  
Location Name: Sack 8-11  
Location ID: 320509




Photo 7 Capped casing.

Photo 8 Capped casing