

# Inspection Photos

API: 061-05061

Operator: WESTERN OPERATING COMPANY

Inspection Date: 4/25/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05061 | Date: 4/25/2022

## Inspection Photos



**Photo 1.** Facing northwest toward the tank battery location. 38.431062 / -102.480275.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05061 | Date: 4/25/2022

## Inspection Photos



**Photo 2.** There is still undesirable weed debris caught in the electric fence which will ground out the electric fence. The weed debris needs to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05061 | Date: 4/25/2022

## Inspection Photos



**Photo 3.** Facing northeast toward the tank battery. The berm around the battery has been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05061 | Date: 4/25/2022

## Inspection Photos



**Photo 4.** Facing toward the well at the west side of the location. Sign is posted at wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05061 | Date: 4/25/2022

## Inspection Photos



**Photo 5.** The electric fence around the location has been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-05061 | Date: 4/25/2022