

Inspection Photos

API: 061-06866

Operator: NAVEX RESOURCES LLC

Inspection Date: 4/25/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06866 - Date: 4/25/2022

Inspection Photos



Photo 1. Facing east toward the access road. Most of the former road has revegetated but there are some areas that have not.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06866 - Date: 4/25/2022

Inspection Photos



Photo 2. Facing east toward the location. Most of the location does not have vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06866 - Date: 4/25/2022

Inspection Photos



Photo 3. Center of the location facing west. Most of the location does not have vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06866 - Date: 4/25/2022

Inspection Photos



Photo 4. View of ground cover show bare soils with no vegetation.



Inspection Photos



Photo 5. Facing south toward the surrounding undisturbed pasture which consists of Blue grama, Sand drop seed, among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06866 - Date: 4/25/2022