

Inspection Photos
Location Name: Miller 1-17
Location ID: 328938



Photo 1 WH sign.

Photo 2 WH

Inspection Photos
Location Name: Miller 1-17
Location ID: 328938



Photo 3 TB sign.

Photo 4 TB

Inspection Photos
Location Name: Miller 1-17
Location ID: 328938



Photo 5 Horiz. Heated Separators

Photo 6 ECD

Inspection Photos
Location Name: Miller 1-17
Location ID: 328938



Photo 7 Gas Meter Run, card indicates current calibration

Photo 8 Gas Meter Runs, cards indicates current calibration