

Inspection Photos  
Location Name: Dechant-State 1  
Location ID: 336321



Photo 1 WH sign.

Photo 2 WH, stained soil

**Inspection Photos**  
**Location Name: Dechant-State 1**  
**Location ID: 336321**



**Photo 3 stained soil around wellsite.**



**Photo 4 ancillary equip.**

Inspection Photos  
Location Name: Dechant-State 1  
Location ID: 336321



Photo 5 TB sign

Photo 6 TB, paint faded and peeling making it hard to see placards and labels



**Inspection Photos**  
**Location Name: Dechant-State 1**  
**Location ID: 336321**



**Photo 7 Horiz. Heated Sep. and ECD**

**Photo 6 8 Flow line manifold**



**Inspection Photos**  
**Location Name: Dechant-State 1**  
**Location ID: 336321**



**Photo 9 Flow line**



**Photo 10 unused pipe by tank battery location**

**Inspection Photos**  
**Location Name: Dechant-State 1**  
**Location ID: 336321**



**Photo 11 unused flow lines, cement pad no LOTO**

**Photo 12 unused flow lines no LOTO**

**Inspection Photos**  
**Location Name: Dechant-State 1**  
**Location ID: 336321**



**Photo 13 Compressor house**

**Photo 14 inside compressor house**

**Inspection Photos**  
**Location Name: Dechant-State 1**  
**Location ID: 336321**



**Photo 15 Gas Meter Run**