

Inspection Photos
Location Name: Longhorn V41-10-9XRLNB
Location ID: 450201



Photo #1 Location



Photo #2 Reference to ECD

Inspection Photos
Location Name: Longhorn V41-10-9XRLNB
Location ID: 450201



Photo #3 Missing Bird Protector



Photo #4 Unmarked Risers

Inspection Photos
Location Name: Longhorn V41-10-9XRLNB
Location ID: 450201



Photo #5 Unused Equipment



Photo #6 Trash & Stained soil

Inspection Photos
Location Name: Longhorn V41-10-9XRLNB
Location ID: 450201



Photo #7 Stained soil



Photo #8 Stained soil