

Inspection Photos
Location Name: Sonic Star 1101 PAD
Location ID: 442437



Photo 1 – Tank Battery Sign



Photo 2 – Wellheads



Inspection Photos
Location Name: Sonic Star 1101 PAD
Location ID: 442437



Photo 3 – Tank Battery and LACT



Photo 4 – Gas Lift Injection Meters



Inspection Photos
Location Name: Sonic Star 1101 PAD
Location ID: 442437



Photo 5 – Tank missing Labels



Photo 6 – ECD



Inspection Photos
Location Name: Sonic Star 1101 PAD
Location ID: 442437



Photo 7 – VRUs



Photo 8 – Flowline Headers

Inspection Photos
Location Name: Sonic Star 1101 PAD
Location ID: 442437



Photo 9 – Separators



Photo 10 – Compressor

Inspection Photos
Location Name: Sonic Star 1101 PAD
Location ID: 442437



Photo 11 – Compressor



Photo 12 – Tanks Battery

Inspection Photos
Location Name: Sonic Star 1101 PAD
Location ID: 442437



Photo 13 – Tank Missing Labels