

Inspection Photos
Location Name: Fiscus Federal 2627 PAD
Location ID: 471794



Photo 1 – Wellheads

Photo 2 – 05H Wellhead – Missing Sign

Inspection Photos
Location Name: Fiscus Federal 2627 PAD
Location ID: 471794



Photo 3 – 04H Wellhead – Missing Sign

Photo 4 – 03H Wellhead – Missing Sign

Inspection Photos
Location Name: Fiscus Federal 2627 PAD
Location ID: 471794



Photo 5 – Gas Lift Injection Meter Shed



Photo 6 – Compressor

Inspection Photos
Location Name: Fiscus Federal 2627 PAD
Location ID: 471794



Photo 7 – Compressor

Photo 8 – Wellhead Headers

Inspection Photos
Location Name: Fiscus Federal 2627 PAD
Location ID: 471794



Photo 9 – Separators

Photo 10 – VRUs

Inspection Photos
Location Name: Fiscus Federal 2627 PAD
Location ID: 471794



Photo 11 – ECD



Photo 12 – East Side – Second of the North – Content and Capacity

Inspection Photos
Location Name: Fiscus Federal 2627 PAD
Location ID: 471794



Photo 13 – Tank Battery

Photo 14 – Tanks Battery Signs Tank missing Labels – NFPA, Content and Capacity

Inspection Photos
Location Name: Fiscus Federal 2627 PAD
Location ID: 471794




Photo 15 – Unmarked Riser



Photo 16 – Compressor

Inspection Photos
Location Name: Fiscus Federal 2627 PAD
Location ID: 471794



Photo 17 – Cellar Covers

Photo 18 – Silt Fence in disrepair

Inspection Photos
Location Name: Fiscus Federal 2627 PAD
Location ID: 471794



Photo 19 – Silt Fence in disrepair

Photo 20 – Silt Fence in disrepair

Inspection Photos
Location Name: Fiscus Federal 2627 PAD
Location ID: 471794



Photo 21 – Silt Fence in disrepair

Photo 22 – Silt Fence in disrepair