

Inspection Photos
Location Name: Linnebur#1
Location ID: 319884



Photo#1 Production Tanks



Photo#2 Separator

Inspection Photos
Location Name: Linnebur#1
Location ID: 319884



Photo#3 Pumpjack



Photo#4 No bull plug on load out line.

Inspection Photos
Location Name: Linnebur#1
Location ID: 319884



Photo#5 No bull plug on load out line.



Photo#6 Gap under production tanks

Inspection Photos
Location Name: Linnebur#1
Location ID: 319884



Photo#7 Gap under production tanks



Photo#8 Gap under production tanks



Inspection Photos
Location Name: Linnebur#1
Location ID: 319884



Photo#9 Gap under production tanks

