



Inspection Photos
facility ID 430124
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #1 Sign at entry to location



Inspection Photos
facility ID 430124
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #2 Tank battery. 3-400 bbl tanks



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
facility ID 430124
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #3 space inside tank battery for another tank. Note Pig launch station in background, this should be addressed in the Form 27.



Inspection Photos
facility ID 430124
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #4 3 tanks



Inspection Photos
facility ID 430124

Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #5 stored equipment. Pipeline infrastructure.



Inspection Photos
facility ID 430124
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #6 same as photo#5



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
facility ID 430124
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #7 stored equipment



Inspection Photos
facility ID 430124
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #8 stored equipment. Transformers shall be identified on the rule 911 Form 27.



Inspection Photos
facility ID 430124
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #9 stored equipment



Inspection Photos
facility ID 430124
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #10 gas treatment equipment.



Inspection Photos
facility ID 430124
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #11 flowlines.



Inspection Photos
facility ID 430124
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #12 stored equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
facility ID 430124
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel



Photo #13 gas treatment and transmission.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Inspection Photos
facility ID 430124
Inspection Date: 4/26/2022
All Photos taken by Kris Neidel

Photo #14 stored equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources