

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2SWSW

Location ID: 334880



Photo #6554 from entrance to location.



Photo #6555 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2SWSW

Location ID: 334880



Photo #6556 Loadline open ended.



Photo #6557 Stained soils inside tank containment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2SWSW

Location ID: 334880



Photo #6558 Vent pipe on tank open ended.