

Inspection Photos

API: 071-09420

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/29/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09420 | Date: 4/29/2022

Inspection Photos



Photo 1. Facing west along the access road. The road is stabilized with gravel and vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 4/29/2022

Inspection Photos



Photo 2. The abandoned pipe risers have been removed and disturbance areas are reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 4/29/2022

Inspection Photos



Photo 3. Facing west along the access road. The road is stabilized with gravel and vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 4/29/2022

Inspection Photos



Photo 4. Facing northwest toward the access road and location that remains per variance request.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09420 | Date: 4/29/2022