

PHOTOGRAPHIC LOG



Photograph 1: Heater Treater release point, day of discovery, view northwest



Photograph 2: Impact to adjacent field to west, day of discovery, view west



Photograph 3: Impact west and southwest of heater treater and adjacent field to west, day of discovery, view northwest



Photograph 4: Heater Treater release point, day of discovery, view north

PHOTOGRAPHIC LOG



Photograph 5: Excavated area of impact east of heater treater, release point at gasket behind small tank, view northwest



Photograph 6: Excavating impact west of heater treater, view north




Photograph 7: Excavated area of impact east of heater treater, release point at gasket behind panels, view southwest



Photograph 8: Heater treater, shed and backfilled area of impact removed within heater treater secondary containment, release point at gasket behind panels, view southwest

PHOTOGRAPHIC LOG



Photograph 9: Excavated area of impact north of heater treater, view south



Photograph 10: Excavated areas of impact west of heater treater, view east



Photograph 11: Excavated area west of heater treater, view east



Photograph 12: Backfilled area of impact removed within east side of heater treater secondary containment, release point at gasket behind panels, view south

PHOTOGRAPHIC LOG



Photograph 13: Excavated area of impact on adjacent property to west, view east



Photograph 14: Excavated area of impact on adjacent property to west, view southwest



Photograph 15: Background sample location in adjacent property to west, view west



Photograph 16: Excavated area of impact on adjacent property to west, view east

PHOTOGRAPHIC LOG



Photograph 17: Background sample location south central pad, impacted soil stockpile to north, view north



Photograph 18: Excavated area of impact in adjacent field to west, view southwest



Photograph 19: Temporary stockpile of excavated impacted soil, central pad, view northeast