

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

08/17/2021

Document Number:

402782495

**ANALYTICAL SAMPLE DATA SUBMITTAL FORM**

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

**Operator Information**

OGCC Operator Number: <u>10705</u>	Contact Person: <u>Mackenzie Smith</u>
Company Name: <u>EVERGREEN NATURAL RESOURCES LLC</u>	Phone: <u>(303) 2848820</u>
Address: <u>1875 LAWRENCE ST STE 1150</u>	Fax: <u>( )</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>	Email: <u>mackenzie.smith@enrllc.com</u>

**Identification Information**

API Number: <u>05 - -</u>	OGCC Facility ID: <u>119967</u>	Initial Form 19 or 27 Document number: _____
Facility Name: <u>RITA</u>	Facility Number: <u>56</u>	Facility Type: <u>PIT</u>
Location QtrQtr: <u>SWNW</u>	Section: <u>13</u>	Township: <u>34S</u>
	Range: <u>66W</u>	Meridian: <u>6</u>
County: <u>LAS ANIMAS</u>	Field Name: <u>PURGATOIRE RIVER</u>	
Federal, Indian or State Lease Number: _____		

Information Submitted By:

Company Name: <u>EVERGREEN NATURAL RESOURCES LLC</u>	Agent Name: <u>Mackenzie Smith</u>	Title: <u>Production Engineer</u>
Phone Number: <u>303-2848820</u>	Email: <u>mackenzie.smith@enrllc.com</u>	

Rule 909.J Inspection Information

Date the Pit was Inspected 05/06/2021

On inspection the Pit was:  Unlined  Lined  Fenced  Netted

**Sample Location Information:**

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: <u>217928</u>	Facility Name: <u>RITA 56</u>	Facility Type: <u>Oil and Gas Well</u>
Location: QtrQtr: <u>SWNW</u>	Sec: <u>13</u>	Twp: <u>34S</u>
	Range: <u>66W</u>	Meridian: <u>6</u>
County Name: <u>LAS ANIMAS</u>	Latitude: <u>37.085830</u>	Longitude: <u>-104.739030</u>

**Sample Information:**

The following Sample Information has been reviewed by the COGCC:

Batch ID: <u>90523</u>	Document Name: <u>EDD2</u>	File Name: <u>217928 - EDD2 - 08112021.xlsx</u>
SampleType: _____	Matrix: _____	
Facility ID: <u>217928</u>	Sample ID: <u>627135</u>	Sample Name: <u>Brown Recluse 12-13</u>
	Sample Date: <u>07/08/2021</u>	
Collection Point: <u>WellHead</u>	Matrix: <u>WATER</u>	Pre Post: <u>Rule 909.j inital sample</u>
Project Number: _____	Remediation Number: _____	Complaint Number: _____
		NOAV Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: <u>TestAmerica Inc.</u>
		Lab Sample ID: <u>280-150633-2</u>

Batch ID: 90522 Document Name: EDD1 File Name: 217928 - EDD1 - 07222021.xlsx

SampleType: \_\_\_\_\_ Matrix: \_\_\_\_\_

Facility ID: 217928 Sample ID: 627134 Sample Name: Brown Recluse 12-13 Sample Date: 07/08/2021

Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample

Project Number: \_\_\_\_\_ Remediation Number: \_\_\_\_\_ Complaint Number: \_\_\_\_\_ NOAV Number: \_\_\_\_\_

Inspection Number: \_\_\_\_\_ Spill Number: \_\_\_\_\_ Laboratory: TestAmerica Inc. Lab Sample ID: 280-150633-2

**Sample Facility Attachment:**

Facility ID	Attach Num	File Name	Document Name	File Type
217928	402782531	217928 - Report1 - 07222021.pdf	Analytical Laboratory Report	PDF
217928	402782534	217928 - Report2 - 08112021.pdf	Analytical Laboratory Report	PDF

**Sample COGCC Well Related:**

No Sample COGCC Well Related Information Provided.

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	05/02/2022
Total: 1 comment(s)		