

Inspection Photos

Location Name: KPK Sack Tank Battery

Location: 319867, API: 05-001-07059



One of several spoils piles with inadequate stormwater BMPs.



Open excavations with inadequate fencing.

Inspection Photos

Location Name: KPK Sack Tank Battery

Location: 319867, API: 05-001-07059



Trash



Trash

Inspection Photos

Location Name: KPK Sack Tank Battery

Location: 319867, API: 05-001-07059



Perimeter Fence had been cut and vehicles had been driven to another facility.



Tire tracks extending from the tank battery to the O&G well in the background.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: KPK Sack Tank Battery

Location: 319867, API: 05-001-07059



Cutting and capping the Sack 1 (05-001-07059). Note that the tire tracks crossing the field match the welding truck and the backhoe in the background.

Cutting and capping the Sack 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: KPK Sack Tank Battery
Location: 319867, API: 05-001-07059



Lifting the cut casing.



Lifting the cut casing.



Inspection Photos
Location Name: KPK Sack Tank Battery
Location: 319867, API: 05-001-07059



Lifting the cut casing.



Lifting the cut casing.

Inspection Photos

Location Name: KPK Sack Tank Battery

Location: 319867, API: 05-001-07059



Capping the well.



Capping the well.