

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION Receive Date: 08/30/2021 Document Number: 402796603

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 10705 Contact Person: Mackenzie Smith Company Name: EVERGREEN NATURAL RESOURCES LLC Phone: (303) 2848820 Address: 1875 LAWRENCE ST STE 1150 Fax: ( ) City: DENVER State: CO Zip: 80202 Email: mackenzie.smith@enrllc.com

Identification Information

API Number: 05 - - OGCC Facility ID: 117614 Initial Form 19 or 27 Document number: Facility Name: RITA HILL RANCH 46 Facility Number: Facility Type: PIT Location QtrQtr: SESE Section: 11 Township: 34S Range: 66W Meridian: 6 County: LAS ANIMAS Field Name: PURGATOIRE RIVER Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: EVERGREEN NATURAL RESOURCES LLC Agent Name: Mackenzie Smith Title: Production Engineer Phone Number: 303-2848820 Email: mackenzie.smith@enrllc.com

Rule 909.J Inspection Information

Date the Pit was Inspected 04/27/2021 On inspection the Pit was: [X] Unlined [ ] Lined [ ] Fenced [ ] Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 217895 Facility Name: RITA 46 Facility Type: Oil and Gas Well Location: QtrQtr: SESE Sec: 11 Twp: 34S Range: 66W Meridian: 6 County Name: LAS ANIMAS Latitude: 37.094410 Longitude: -104.742470

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 90884 Document Name: EDD2 File Name: 217895 - EDD2 - 8.30.2021.xlsx SampleType: Matrix: Facility ID: 217895 Sample ID: 627492 Sample Name: Bat 44-11 Sample Date: 07/22/2021 Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample Project Number: Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: TestAmerica Inc. Lab Sample ID: 280-151086-1

Batch ID: 90883 Document Name: EDD1 File Name: 217895 - EDD1 - 8.5.2021.xlsx

SampleType: \_\_\_\_\_ Matrix: \_\_\_\_\_

Facility ID: 217895 Sample ID: 627491 Sample Name: Bat 44-11 Sample Date: 07/22/2021

Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample

Project Number: \_\_\_\_\_ Remediation Number: \_\_\_\_\_ Complaint Number: \_\_\_\_\_ NOAV Number: \_\_\_\_\_

Inspection Number: \_\_\_\_\_ Spill Number: \_\_\_\_\_ Laboratory: TestAmerica Inc. Lab Sample ID: 280-151086-1

**Sample Facility Attachment:**

Facility ID	Attach Num	File Name	Document Name	File Type
217895	402796604	217895 - Report1 - 8.5.2021.pdf	Analytical Laboratory Report	PDF
217895	402796606	217895 - Report2 - 8.30.2021.pdf	Analytical Laboratory Report	PDF

**Sample COGCC Well Related:**

No Sample COGCC Well Related Information Provided.

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	05/03/2022
Total: 1 comment(s)		