

Inspection Photos

Location Name: NOFFSINGER-66N64W /33NWNE

Location #: 327171



Photo #1

Noffsinger 31-33 (05-123-14260) Wellsite

Temporarily Abandoned | TA



Photo #2

Noffsinger 31-33 Battery site

Abandoned: ALL Equipment Removed

Formerly served:

Noffsinger 11-33 ; Plugged & Abandoned | PA

