

Inspection Photos
Location Name: Ferguson#3
Location ID: 319718



Photo#1 Pumpjack



Photo#2 Stuffing box leaking causing stained soil

Inspection Photos
Location Name: Ferguson#3
Location ID: 319718



Photo#3 Stuffing box leaking causing stained soil



Photo#4 Stuffing box leaking causing stained soil