

Final Reclamation Inspection

April 27, 2022

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 333129

Inspection Document #: 697503895

Weld County, CO

SESW Section 34 T1N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SELTZER #24-34
Location ID: 333129



Photo 1. Photo taken from the well location, facing South. Photo illustrates the well location has little to no establishment of desirable plant species. Establishment appears to be limited to the central location (note arrows are pointing to the green vegetation). The northern and southern well location lack establishment.

Inspection Photos
Location Name: SELTZER #24-34
Location ID: 333129



Photo 2. Photo taken from the southern the well location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: SELTZER #24-34
Location ID: 333129



Photo 3. Photo taken west of the well location, facing East. Photo illustrates the well location (red arrows) in the background and the reference area vegetation in the foreground demonstrating the lack of establishment.



Inspection Photos
Location Name: SELTZER #24-34
Location ID: 333129



Photo 4. Reference photo taken west of the well location, facing East.