


Inspection Photos
Location Name: Magoon Federal 2, 067-08326
Location ID: 326571



IMG-0004, Site overview



IMG-0016, Produced water tank hatch properly secure

Inspection Photos

Location Name: Magoon Federal 2, 067-08326

Location ID: 326571



IMG-0012, Obstructed produced water tank placard



IMG-0013, Produced water tank placard facing inward