

Inspection Photos

5/2/2022

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 334089

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334089



May 2, 2022
39.39971687N 108.05028851W



May 2, 2022
39.39971744N 108.05028701W

Photo 1: Photos taken from the south end of the Location. Photos 1-2 provide an overview of the Location from northwest, north to northeast.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334089



May 2, 2022
39.3997166N 108.05028644W

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334089



Photo 3: Photos provide example of the interim areas; interim areas of the Location meet COGCC 1003 reclamation standards. Vegetation observed is predominantly desirable, perennial plant species with a uniform establishment. Continue to monitor and maintain interim areas until site receives a passing final inspection.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334089



May 2, 2022
39.3672248N 108.1664001W



May 2, 2022
39.40020272N 108.05050795W

Photo 4: Photos show subsidence issues are becoming evident along the flowline path between the former Day Break 36-2BB (PA 36) well and the separator. Advise maintenance to ensure pad remains stabilized.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334089



Photo 5: Photo taken from the northeast end of the Location. Photo shows unmarked anchor on Location.

