

Inspection Photos

5/2/2022

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 334682

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334682



May 2, 2022
39.41820102N 108.02246642W



May 2, 2022
39.41820263N 108.02246822W

Photo 1: Photos taken from the south end of the Location. Photos 1-2 provide an overview of the Location from northwest, north, northeast to east.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334682



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334682



Photo 3: Photos taken from the soil stockpile on the north end of the Location, facing northwest, north. Photo left shows areas of the berm where vegetation is predominantly a cheatgrass monoculture (left of yellow line). Photo right shows areas on the north and east facing slopes of the berm where desirable perennial vegetative establishment is evident and uniform.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334682



May 2, 2022
39.4262087N 108.0364707W



May 2, 2022
39.41896642N 108.02248969W

Photo 4: Photos taken from the soil stockpile on the north end of the Location, facing west, northwest. Photo left shows areas of the berm where vegetation is predominantly a cheatgrass monoculture (left of yellow line). Yellow arrow shows clumps of desirable plants within areas of cheatgrass. Photo right shows areas on the north and west facing slopes of the berm where desirable perennial vegetative establishment is evident and uniform.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334682



Photo 5: See comments under photo 4.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334682



May 2, 2022
39.41858277N 108.02289979W

Photo 6: Photo taken from the western interim areas of the Location. Photo shows example of areas beyond the berms that have achieved uniform, desirable perennial vegetative establishment. Though cheatgrass is evident within these areas, it is not the dominant species.