

Inspection Photos

5/2/2022

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 334983

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334983



Photo 1: Photos taken from the north end of the Location. Photos 1-2 provide an overview of the Location from east, southeast, southwest to west.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334983



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334983



Photo 4: Photo taken from the north end of the Location. Photo shows erosion degradation at the sediment trap control measure. Hard hat used for reference.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334983



Photo 5: Photo shows unused pipe stored next to pipeline.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334983



Photo 6: Photos taken from the interim areas of the Location. Photos examples showing interim areas have met 1003 standards.