

Inspection Photos

5/2/2022

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 311692

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311692



Photo 1: Photos taken from the north end of the Location. Photos 1-2 provide an overview of the Location from east, southeast, southwest to west.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311692



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311692



Photo 3: Photo taken from the southeast end of the Location, facing west. Photos 3-8 show areas along the slopes on the south end of the Location, where erosion degradation resulting in mass soil migration from the slopes is evident. Areas require additional reclamation and stabilization.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311692



Photo 4: See comments under photo 3.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311692



Photo 5: See comments under photo 3.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311692



Photo 6: See comments under photo 3.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311692



Photo 7: See comments under photo 3.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311692



Photo 8: See comments under photo 3.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311692



Photo 9: Photos taken from the northeastern-most condensate tank on the Location. Photo shows rusting and possible integrity issues at the base of the tank, as well as stained soils within the same area.