

# Final Reclamation Inspection

April 27, 2022

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 333142

Inspection Document #: 697503897

Weld County, CO

SWSW Section 34 T1N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: SELTZER #14-34  
Location ID: 333142



**Photo 1.** Photo taken from the eastern well location access road, facing Northwest. Photo illustrates the well location access road has some establishment of desirable plant species.

Inspection Photos  
Location Name: SELTZER #14-34  
Location ID: 333142



**Photo 2.** Photo taken from the well location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: SELTZER #14-34  
Location ID: 333142



**Photo 3.** Photo taken from the well location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: SELTZER #14-34  
Location ID: 333142



**Photo 4.** Photo taken from the well location, facing South. See comments under Photo 1.

Inspection Photos  
Location Name: SELTZER #14-34  
Location ID: 333142



**Photo 5.** Photo taken from the well location, facing South. See comments under Photo 1.