

Final Reclamation Inspection

April 27, 2022

Operator: PETROSHARE CORPORATION - 10454

Location ID: 320465

Inspection Document #: 697503905

Adams County, CO

SENW Section 2 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GUTHRIE #22-2
Location ID: 320465



Photo 1. Photo taken from the northern well location access road, facing South. Photo illustrates Operator has failed to comply with Rule 1004 standards and has not removed gravel, recontour and perform subsequent final reclamation (i.e., compaction alleviation, etc..).

Inspection Photos
Location Name: GUTHRIE #22-2
Location ID: 320465



Photo 2. Reference photo taken from the northern well location access road, facing East.