

FORM  
43Rev  
05/21

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

09/01/2021

Document Number:

402798993

## ANALYTICAL SAMPLE DATA SUBMITTAL FORM

### Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

### Operator Information

OGCC Operator Number: 10705 Contact Person: Mackenzie Smith  
Company Name: EVERGREEN NATURAL RESOURCES LLC Phone: (303) 2848820  
Address: 1875 LAWRENCE ST STE 1150 Fax: ( )  
City: DENVER State: CO Zip: 80202 Email: mackenzie.smith@enrllc.com

### Identification Information

API Number: 05 - - OGCC Facility ID: 117830 Initial Form 19 or 27 Document number:   
Facility Name: RITA HILL RANCH 53 Facility Number: Facility Type: PIT  
Location QtrQtr: SWNE Section: 24 Township: 34S Range: 65W Meridian: 6  
County: LAS ANIMAS Field Name: PURGATOIRE RIVER  
Federal, Indian or State Lease Number:

### Information Submitted By:

Company Name: EVERGREEN NATURAL RESOURCES LLC Agent Name: Mackenzie Smith Title: Production Engineer  
Phone Number: 303-2848820 Email: mackenzie.smith@enrllc.com

### Rule 909.J Inspection Information

Date the Pit was Inspected 05/06/2021  
On inspection the Pit was: ☒ Unlined ☐ Lined ☐ Fenced ☐ Netted

### Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 217842 Facility Name: RITA 53 Facility Type: Oil and Gas Well  
Location: QtrQtr: SWNE Sec: 24 Twp: 34S Range: 66W Meridian: 6  
County Name: LAS ANIMAS Latitude: 37.071500 Longitude: -104.727500

### Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 90978 Document Name: EDD2 File Name: 217842 - EDD2 - 09012021.xlsx  
SampleType: Matrix:  
Facility ID: 217842 Sample ID: 627591 Sample Name: Llama 32-24 Sample Date: 07/26/2021  
Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample  
Project Number: Remediation Number: Complaint Number: NOAV Number:  
Inspection Number: Spill Number: Laboratory: TestAmerica Inc. Lab Sample ID: 280-151178-2

Batch ID: 90977 Document Name: EDD1 File Name: 217842 - EDD1 - 08122021.xlsx

SampleType: Matrix:

Facility ID: 217842 Sample ID: 627590 Sample Name: Llama 32-24 Sample Date: 07/26/2021

Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample

Project Number: Remediation Number: Complaint Number: NOAV Number:

Inspection Number: Spill Number: Laboratory: TestAmerica Inc. Lab Sample ID: 280-151178-2

**Sample Facility Attachment:**

| Facility ID | Attach Num | File Name                       | Document Name                | File Type |
|-------------|------------|---------------------------------|------------------------------|-----------|
| 217842      | 402798999  | 217842 - Report1 - 08122021.pdf | Analytical Laboratory Report | PDF       |
| 217842      | 402799003  | 217842 - Report2 - 09012021.pdf | Analytical Laboratory Report | PDF       |

**Sample COGCC Well Related:**

No Sample COGCC Well Related Information Provided.

**General Comments**

| <u>User Group</u>   | <u>Comment</u>   | <u>Comment Date</u> |
|---------------------|--|---------------------|
| Environmental       | A task has been opened for the Integrity Group to review the information provided by the operator. | 05/05/2022          |
| Total: 1 comment(s) |  |                     |