

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403032337

Receive Date:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

Report taken by:

OPERATOR INFORMATION

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP	Operator No: 47120	Phone Numbers Phone: (970) 336-3500 Mobile: ()
Address: P O BOX 173779		
City: DENVER	State: CO Zip: 80217-3779	
Contact Person: Phil Hamlin	Email: Phil_Hamlin@oxy.com	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 9787 Initial Form 27 Document #: 200440043

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

No Multiple Facilities

Facility Type: SPILL OR RELEASE	Facility ID: 445591	API #: _____	County Name: WELD
Facility Name: SPILL/RELEASE POINT	Latitude: 40.141908	Longitude: -104.672677	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: SENW	Sec: 16	Twp: 2N	Range: 65W Meridian: 6 Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Rangeland
Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? No
Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Domestic water well approximately 1,050 feet (ft) northwest, building approximately 1,350 ft west, livestock approximately 4,000 ft southeast, and groundwater approximately 45 ft below ground surface (bgs).

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- E&P Waste
- Other E&P Waste
- Non-E&P Waste
- Produced Water
- Workover Fluids
- Oil
- Tank Bottoms
- Condensate
- Pigging Waste
- Drilling Fluids
- Rig Wash
- Drill Cuttings
- Spent Filters
- Pit Bottoms
- Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	GROUNDWATER	See Attached Data	Groundwater Samples/Lab Analysis
Yes	SOILS	54' N-S x 27' E-W x 45' bgs	Soil Samples/Lab Analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

In April 2016, two partially-buried produced water sumps were removed during tank battery deconstruction activities at the Four Way 1 facility. Soil with historical petroleum hydrocarbon impacts were encountered beneath the southern produced water sump. The petroleum hydrocarbon impacted soil was excavated to a depth of approximately 25 ft bgs. Based on August 2016 assessment activities, impacted soil remains in place beneath the backfilled excavation to a depth of approximately 45 ft bgs.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Between April 14 and 21, 2016, twelve soil samples were collected from the excavation for benzene, toluene, ethylbenzene, and total xylenes (BTEX), total petroleum hydrocarbons (TPH), pH, and specific conductance (EC). Laboratory analytical results indicated that benzene, total xylenes, TPH, and pH exceeded the Colorado Oil and Gas Conservation Commission (COGCC) Table 910-1 allowable levels at the base of the excavation. In August 2016, a subsurface assessment was conducted to determine the extent of impacted soil in place. The assessment activities indicated that impacted soil remains in place beneath the backfilled excavation to a depth of approximately 45 ft bgs. Please refer to the Form 27 Update Report submitted to the COGCC on October 28, 2016, for further details. The general site layout, excavation extent, and extent of impacted soil in place are depicted on the Site Map provided as Figure 1.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater monitoring has been conducted on a quarterly basis since August 2016.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 48

Number of soil samples exceeding 915-1 15

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 1458

NA / ND

-- Highest concentration of TPH (mg/kg) 16560

NA Highest concentration of SAR

BTEX > 915-1 Yes

Vertical Extent > 915-1 (in feet) 45

Groundwater

Number of groundwater samples collected 133

Was extent of groundwater contaminated delineated? Yes

Depth to groundwater (below ground surface, in feet) 45'

Number of groundwater monitoring wells installed 6

Number of groundwater samples exceeding 915-1 24

-- Highest concentration of Benzene (µg/l) 1410

-- Highest concentration of Toluene (µg/l) 7200

-- Highest concentration of Ethylbenzene (µg/l) 2460

-- Highest concentration of Xylene (µg/l) 33500

NA Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

 Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

Is further site investigation required?

Petroleum hydrocarbon impacted soil remains in place beneath the backfilled excavation to a depth of approximately 45 ft bgs. Prior to submittal of a No Further Action (NFA) status request, the impacted soil left in place will be reassessed for compliance with COGCC Table 915 allowable levels. A project implementation schedule is included as an attachment.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

The petroleum hydrocarbon impacted soil was excavated to a depth of approximately 25 ft bgs. Approximately 780 cubic yards of petroleum hydrocarbon impacted soil were removed from the excavation and transported to Buffalo Ridge Landfill in Keenesburg, Colorado, for disposal. Petroleum hydrocarbon impacted soil remains in place beneath the backfilled excavation to a depth of approximately 45 ft bgs. Please refer to the Form 27 Update Report submitted to the COGCC on October 28, 2016, for further details regarding the excavation and subsurface assessment activities. The excavation footprint and extent of the petroleum hydrocarbon impacted soil left in place are depicted on the Site Map provided as Figure 1.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Please refer to the Form 27 Update Report submitted to the COGCC on October 28, 2016, for initial remediation activities. Prior to submittal of an NFA status request, the impacted soil left in place beneath the backfilled excavation will be reassessed for compliance with COGCC Table 915 allowable levels. A project implementation schedule is included as an attachment.

Soil Remediation Summary

In Situ

Ex Situ

- Bioremediation (or enhanced bioremediation)
- Chemical oxidation
- Air sparge / Soil vapor extraction
- Natural Attenuation
- Other _____

- Yes Excavate and offsite disposal
- If Yes: Estimated Volume (Cubic Yards) 780
- Name of Licensed Disposal Facility or COGCC Facility ID # _____
- No Excavate and onsite remediation
- Land Treatment
- Bioremediation (or enhanced bioremediation)
- Chemical oxidation
- Other _____

Groundwater Remediation Summary

- No Bioremediation (or enhanced bioremediation)
- No Chemical oxidation
- No Air sparge / Soil vapor extraction
- Yes Natural Attenuation
- No Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Groundwater monitoring wells MW01 through MW06 are sampled on a quarterly basis for the full list of analyses for groundwater in Table 915-1. Upgradient and compliant groundwater monitoring well MW06 was established as a representative background sample for calculating the inorganic parameters in Table 915-1. The Groundwater Elevation Contour Map generated using the April 2022 survey data is provided as Figure 2. The groundwater analytical results are summarized in Table 1, and the laboratory analytical reports for the April 2021, July 2021, October 2021, January 2022, and April 2022 groundwater monitoring events are attached.

Monitoring well MW01 was destroyed as of the April 2022 monitoring event. A replacement groundwater monitoring well will be installed. A project implementation schedule is included as an attachment.

Groundwater monitoring will continue on a quarterly basis until a No Further Action status request is warranted.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report
 Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? Yes

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

NA

Volume of E&P Waste (solid) in cubic yards 780

E&P waste (solid) description Petroleum hydrocarbon impacted soil

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: Buffalo Ridge Landfill in Keenesburg, Colorado

Volume of E&P Waste (liquid) in barrels 0

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

- Compliant with Rule 913.h.(1).
- Compliant with Rule 913.h.(2).
- Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the COGCC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The Kerr-McGee tank battery facility was deconstructed. The site was restored to its pre-release grade.

Is the described reclamation complete? No _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 04/21/2016

Actual Spill or Release date, or date of discovery. 04/20/2016

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 04/14/2016

Proposed site investigation commencement. 04/20/2016

Proposed completion of site investigation. 08/09/2016

REMEDIAL ACTION DATES

Proposed start date of Remediation. 04/20/2016

Proposed date of completion of Remediation. _____

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Phil Hamlin _____

Title: Senior Environmental Rep. _____

Submit Date: _____

Email: Phil_Hamlin@oxy.com _____

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

Remediation Project Number: 9787 _____

COA Type**Description**

--	--

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

403033156	ANALYTICAL RESULTS
403033208	GROUND WATER ELEVATION MAP
403033264	SITE MAP
403039250	IMPLEMENTATION SCHEDULE

Total Attach: 4 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)