

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /33SWSE

Location ID: 334870



Photo #6599 from entrance to location.



Photo #6600 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /33SWSE

Location ID: 334870



Photo #6602 Loadline open ended.



Photo #6603 Vent pipe on tank open ended.