

**Inspection Photos**  
**Location Name: McCallum Unit 87**  
**Location ID: 324653**



**Photo 1. Overview of location taken facing northwest.  
Stained soil on location.**



**Photo 2. No bradenhead access apparent.**

