

**Inspection Photos**  
**Location Name: McCallum Unit 86**  
**Location ID: 324652**



**Photo 1. Overview of location taken facing north. Stained soil on location.**



**Photo 2. No bradenhead access apparent. Stained soil at wellhead.**

